



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining


MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

February 06, 2013

Reviewed: 

Mine Name: Peoa Blonde Quarry	Permit Number: M/043/0012
Operator Name: Mountain Valley Stone, Inc.	Inspection Date: October 19, 2011
Inspector(s): L Hepler	Time: 8:00 AM
Other Participants: Operators Representative	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 10-16-2011 **Bond Amount:** \$54,900 **Permit fee** is up to date for 2012, 2013 fees are being processed

Purpose of Inspection: Routine annual Inspection. This site was inspected as a large mine site on 09/08/2010.

Inspection Summary: Overall Mine site is well kept and organized. Operator has been using the site for crushing. Every effort should be made to salvage top soil from the site prior to mining.

Photos were taken to document site conditions.

Conclusions and Recommendations: Permit NOI needs to be updated based on Operators plan. Bond needs to be increased, based on current disturbance on the ground. Weeds need to be controlled, as shown in attached photos. Operator has 30 days to submit an interim bond. Operator needs to define area for growth medium. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:eb

cc: Mountain Valley Stone - Robert Hicken

O:\M043-Summit\M0430012-PcoaQuarry\inspections\Insp-10192011.doc





Access Road



Previous Operators stockpile



Wetland area



Wetland area



Crushing Area



Crushing Area



Crushing Area



Crushing Area